Prepared By: City of Charlotte Housing & Neighborhood Services 600 E. Trade Street Charlotte, NC 28202 (704) 336-7600

Property Details	Addendur						
Address:	2329 Thornton Rd	Own	er:	Franc	cedia Miller	•	
	Charlotte, NC 28208	Own	er Phone:	Hom	e: (704) 391	-2009	
Structure Type:	Single Unit	Prog	ram(s):	Lead	Safe		
Square Feet:	1174			Tested- NO LEAD Safe Home FY 2017			
Year Built:	1962				Home FY 2		
Property Value:	68800			Lead	Safe 2016		•
Tax Parcel:	0611308						
Census Tract:							
Property Zone:	Council District 3						
Repair Category: <u>Description</u>	00.0 General Requirements		*	<u>Floor</u>	Room		<u>Exterior</u>
Dumpster After procuring all redebris using dust col	quired permits, place AS MANY roll-off ntrol methods. Remove dumpster and r				ging the site	. Colle	
Dumpster After procuring all redebris using dust col	ntrol methods. Remove dumpster and r		of the dum		ging the site	. Colle	ct construction
Dumpster After procuring all redebris using dust col	ntrol methods. Remove dumpster and r	epair any evidence	of the dum		ging the site	. Colle	ct construction
Dumpster After procuring all redebris using dust colaway daily using dur	ntrol methods. Remove dumpster and r	epair any evidence	of the dum		ging the site use. Contra Quantity	. Collector m	ct construction ay haul debris
Dumpster After procuring all redebris using dust con away daily using dur	ntrol methods. Remove dumpster and r	epair any evidence Bid Cost:	of the dum		ging the site use. Contra Quantity	. Collector m	ct construction ay haul debris Total Cost
Dumpster After procuring all redebris using dust con away daily using dur	ntrol methods. Remove dumpster and r	epair any evidence Bid Cost:	of the dum Base		ging the site use. Contra Quantity	. Collector m	ct construction ay haul debris Total Cost
Dumpster After procuring all redebris using dust coraway daily using dur	ntrol methods. Remove dumpster and r	Bid Cost:	of the dum Base		ging the site use. Contra Quantity	. Collector m	ct construction ay haul debris Total Cost
Dumpster After procuring all redebris using dust colaway daily using dur Portable Toilet Provide temporary to	ntrol methods. Remove dumpster and r	Bid Cost:	Base ·		ging the site use. Contra Quantity GENERA	. Collector m	ct construction ay haul debris Total Cost
Dumpster After procuring all redebris using dust collaway daily using dur Portable Toilet Provide temporary to	ntrol methods. Remove dumpster and r np trailers. bilet facilities from job start until approve	Bid Cost:	Base lities.		ging the site use. Contra Quantity GENERA	. Collector m	ct construction ay haul debris Total Cost
Dumpster After procuring all redebris using dust colaway daily using dur Portable Toilet Provide temporary to Repair Category: Description	ntrol methods. Remove dumpster and response trailers. Silet facilities from job start until approve the start approve the start until approve the sta	Bid Cost:	Base lities.	xx	Quantity Quantity Quantity Quantity	. Collector m	ct construction ay haul debris Total Cost RUIREMENERSerior Total Cost
After procuring all redebris using dust coraway daily using durformally using durformally description Exterminate for termit	ntrol methods. Remove dumpster and response trailers. Silet facilities from job start until approve the start approve the start until approve the sta	Bid Cost: Bid Cost: Bid Cost:	Base Base	x X X Floor	Quantity Quantity Quantity Room	. Collector m	ct construction ay haul debris Total Cost RUIREMENERSerior Total Cost Exterior
After procuring all redebris using dust coraway daily using durfur Portable Toilet Provide temporary to Provide temporary to Pescription Exterminate Termit Exterminate for term	ntrol methods. Remove dumpster and respectively. In trailers. In trail	Bid Cost: Bid Cost: Bid Cost:	Base Base Base	x X X Floor	Quantity Quantity Quantity Room	. Collector m	ct construction ay haul debris Total Cost RUIREMENERSerior Total Cost Exterior

Repair Category: 04.0 Exterior Carpentry & Wall Framing **Exterior** Description <u>Floor</u> Room **EXTERIOR** Vinyl Soffit, Aluminum Fascia & Siding Repair Exterior Install vented vinyl soffit to roof edges, ensuring existing soffit is opened up to allow attic ventilation. Install solid vinyl soffit to all gable overhangs. Wrap all facia and wood trim with PVC coated aluminum coil stock. (11.4) Repair / replace any decayed siding. Most decay occurs near bottom of sheathing . Add a continuous horizontal 2" band approximately 36" from bottom of sheathing. Any decayed sheathing below, remove and replace, paint to match. Quantity **Total Cost** Prep & Paint Exterior Surfaces - EXTERIOR Prep and paint all exterior painted surfaces. Properly dispose all loose materials. Secure or replace all loose, broken, rotted or deteriorated materials. Caulk and fill all cracks, voids, holes, etc. prior to applying 25-year or better Low VOC paint. Owners choice of color. All work to be done in a neat & professional manner. Use care to protect all surfaces not intended for paint coverage. **Total Cost** Repair Category: 06.0 Roof, Chimney, Gutters & Downspouts Room **Exterior** Description <u>Floor</u> **EXTERIOR Tear Off & Reroof Shingles** Exterior Remove and dispose of existing roofing, inspect and repair roof deck (include 192 sq.ft. of decking replacement in bid) and install new 30 year architectural shingles. Include ice and water shield at all roof edges, felt paper, shingle over ridge vent, boots, flashing and all necessary accessories. (13.3) Base **Total Cost** Quantity

Repair Category: 08.0 Doors & Windows				
Description		Floo	or Room	Exterior
Vinyl Window				
Use Slider System Windows Dispose of window units and any security bars. Field mea windows including half screens. Insulate rough opening. I Exterior trim to be wrapped in PVC coated aluminum coil installation is to include repairing any damaged header, fr joists and sill.	nstall new extensior as needed. Repair a	n jambs, casing a all areas disturbe	and sill as need d by removal a	ed, prime and paint. Ind installation. This
	Bid Cost:	Х		=
		X Base	Quantity	Total Cost
Sliding Glass Patio Door				
Remove and dispose of existing door, frame and threshol	d. Install new Energ		nung exterior v	
screen and locking hardware. Insulate cavity. New casing any damaged header, door framing, wall framing, sub-floo	or, floor joists, band	joists, and sill.		
-	or, floor joists, band	joists, and sill.		
-	or, floor joists, band			
any damaged header, door framing, wall framing, sub-floo	or, floor joists, band	joists, and sill.	Quantity	
any damaged header, door framing, wall framing, sub-floo Repair Category: 10.0 Electrical	or, floor joists, band	joists, and sillX_ Base	Quantity	= Total Cost <u>Exterior</u>
any damaged header, door framing, wall framing, sub-floor Repair Category: 10.0 Electrical Description	Bid Cost:	joists, and sill. _X Base <u>Flo</u> c	Quantity o <u>r Room</u> KITCHEN	= Total Cost <u>Exterior</u>
any damaged header, door framing, wall framing, sub-floor Repair Category: 10.0 Electrical Description GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, du	Bid Cost:	joists, and sill. X Base Floo	Quantity or <u>Room</u> KITCHEN ange out other	= Total Cost <u>Exterior</u>
any damaged header, door framing, wall framing, sub-floor Repair Category: 10.0 Electrical Description GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, du	Bid Cost:	joists, and sill. _X Base <u>Flo</u> c	Quantity or <u>Room</u> KITCHEN ange out other	= Total Cost <u>Exterior</u>
any damaged header, door framing, wall framing, sub-floor Repair Category: 10.0 Electrical Description GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, du	Bid Cost:	joists, and sill. X Base Floor cover plate. Cha	Quantity or Room KITCHEN ange out other	= Total Cost Exterior countertop outlet with
Repair Category: 10.0 Electrical Description GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, du GFCI Fish wire and repair all tear out as needed.	Bid Cost:	joists, and sill. X Base Floo cover plate. Cha	Quantity Or Room KITCHEN ange out other Quantity BATHRO	Total Cost Exterior countertop outlet with Total Cost OM - MAIN
Repair Category: 10.0 Electrical Description GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, du GFCI Fish wire and repair all tear out as needed. GFCI Receptacle 20 AMP	Bid Cost:	poists, and sill. X Base Floo cover plate. Cha X Base cover plate. Fish	Quantity Or Room KITCHEN ange out other Quantity BATHRO	Total Cost Exterior countertop outlet with Total Cost OM - MAIN

Repair Category: 11.0 Plumbing & Fixtures

Exterior Description <u>Floor</u> Room **KITCHEN**

Double Bowl Sink Complete

Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimming kitchen sink including a single handle metal body faucet, rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, supply lines, full port ball type shut-off valves & escutcheon plates on all supply & drain lines. No copper compression fittings.



Bid Cost:		X=	
	Rase	Quantity	Total Cost

17" Height Commode Replace

BATHROOM - MAIN

Install a 17" height, 2 piece, close coupled, white, vitreous china commode with a maximum water usage per flush of 1.6 gallons. Include plastic or pressed wood white seat, supply pipe, shut-off valve, flap valve and wax seal.




Bid Cost:		X=	=
	Base	Quantity	Total Cost

Bathtub --- 5' Steel Complete

BATHROOM - MAIN

Install a 5' white, enameled, formed steel, tub complete with lever operated pop up drain and overflow, PVC waste, single lever tub/shower diverter with water saving shower head. Install white tile to 5' height at three sides of tub. Use bull-nose verticle & horizontal edging, include horizontal window sill.



Bid Cost:		x =	
	Base	Quantity	Total Cost

Water heater 40 Gallon Gas

Remove existing water heater and all obsolete or deteriorated flue piping and gas line and dispose of properly. Remove and replace any decayed subfloor, joists & plates. Paint interior water tank closet walls.

Install an insulated 40 gallon, glass lined, high recovery gas water heater with a 10 year warranty and an Energy Factor of .61 or greater.

Installation includes PRV valve and extension, drain pan with drain to the exterior, expansion tank, and new gas line and flue piping through the roof as necessary to meet the requirements of the Construction Specifications and all relevant NC Codes.

	Bid Cost:	X		
		Base	Quantity	Total Cost
Repair Category: 12.0 Floor				
Description		Floo	or Room	Exterio
Resilient Flooring			LIVING ROOM	Exterio
Foyer Only (42" x 50") Install 25 year warrantied resilient floor coverir quarter-round at all perimeters to complete ins	- '	ns. Include tra	nsitions and painted o	or stained wood
/ // `	Bid Cost:	x	=	
		Base	Quantity	Total Cost
Floor System Repair			KITCHEN	
Remove all fixtures not built in. Dispose of floall deteriorated wall studs, plates, girder band		_	center, 3/4" subfloor. I	nclude replacing
	Bid Cost:	x_	=	
		Base	Quantity	Total Cost
Resilient Flooring			KITCHEN	
nstall 25 year warrantied resilient floor covering quarter-round at all perimeters to complete ins	· .	ns. Include tra	nsitions and painted o	or stained wood
4	Bid Cost:	х	=	
		Base	Quantity	Total Cost

Resilient Flooring

LAUNDRY / UTILITY

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

0.00000000	88				
	-882				
33370000	-500		*		
	200		200		
2000 000000	4300	المطالة	COLUMN TO		200000
665 EE	20000	ani 324	4		
100	A 30000 1	- 20	2 00000		
- Total	5633E	S - 3 🗪	2000	436.35s.	200
	2003	ALC: U	B00000		SAME (800)
	28	100	5500000	20.38	3.72.00
	March 1	20000	ASSESSED N	- 10 mg	
	AND DOG TO	4.00	C-12		
					ALC: NO.
	6000a		80 T	- 23	1000
	de la serie	Th. 1	W	11135	32500
	BERNOT	dell'a and		. 173	1000
	3000	£			and other
	A CONTRACTOR				3 C200 E
		AND THE	200	1500	82 mm 6
	100,000	Section .	- Ec.	10.498	30000000
	ARCH 12	ക്കുട്ടു	1	100	STREET
	2000 Per	ann an	400	500	EV 2 25
	ant is	2,7600		4023768	00000
	والمسالة	200	Sec. 200	1000	2.54 5.64
		488			
201				1 1 1 1 1 1	SHOW
-//-					
					7.70
					0.00
2000	100				4365

Bid Cost:	,	X=	=
	Base	Quantity	Total Cost

Floor System Repair

BATHROOM - MAIN

Remove all fixtures not built in. Dispose of floor assembly. Install 2"x 10" joists hung 16" on center, 3/4" subfloor. Include replacing all deteriorated band joists and insulating floor to code.

Decay will extend to Utility closet and Hall wall and floor. Plates, studs, drywall, joist and girder repair expected.



Bid Cost:	X_	=	
	Base	Quantity	Total Cost

Resilient Flooring

BATHROOM - MAIN

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

Bid Cost: X =
Base Quantity Total Cost

Repair Category: 13.0 Interior Wall & Trim

Floor I

Room

Exterior

Prep & Paint Room Semi Gloss

KITCHEN

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)




Description

Bid Cost: _		X=	
	Base	Quantity	Total Cost

Prep & Paint Room Semi Gloss

LAUNDRY / UTILITY

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)



Bid Cost:		K	=
	Base	Quantity	Total Cost

Prep & Paint Room Semi Gloss

HALL

Remove or cover hardware and accessories not to be painted. Repair any large cracks & drywall holes. Shoe mold replacement if necessary. Repair loose ceiling finish and match repair.

Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)



Bid Cost:		X=	
	Base	Quantity	Total Cost

Drywall Entire Room

BATHROOM - MAIN

Remove all gypsum, paneling, lathe and plaster or miscellaneous wall coverings to expose framing. Add insulation as required by code. Glue, nail and screw new drywall. Apply tape and 3 coats of joint compound to achieve a professional finish. Wet sand ready for paint. (Also 26.0 - Plaster)



Bid Cost:		x	=
	Base	Quantity	Total Cost

Prep & Paint Room Semi Gloss

BATHROOM - MAIN

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)

500000000000000000000000000000000000000	ST 100 100 100 100 100 100 100 100 100 10	THE REAL PROPERTY.	-0.1 AC	
PER TOTAL STATE	- CO.	-	resident.	
1/21/30/00 TAX				200
Contraction of	OHOLDSON.	1000		
THE RESIDENCE OF THE PARTY OF T				
Control of the last of the las	10000000			
100	OFFICE AND ADDRESS.	manage All		
EXCHANGE BY AN				
100000000000000000000000000000000000000	2010/08/08/09	TOTAL DES		
	200	SERVICE AND	S1000000	
900000000000000000000000000000000000000				
E-0200 FR8-0800	NAME OF TAXABLE PARTY.	MUNICIPAL SOCI		
505000000000000000000000000000000000000		200 Miles		
A CHARLES OF THE	02 S 000 E 15	CARLES SAN		
E1000000000000000000000000000000000000	200000		-	
200000000000000000000000000000000000000		20 May 128		
(\$2000000000000000000000000000000000000		3545 1993		20070
0000000000	100000000000000000000000000000000000000	220		
S-332-S-33-S-32		200 C	2000	೫೫
12/2006		550 333	Britania (
100000000000000000000000000000000000000		250		
and the same of th	Section 1	1200		100
THE RESERVE OF STREET	3	30 B	1000	00000
1000			1000	0.000
17 C 18 C		125	- 1880	
POSTUDOCCO NO.		1211 1111	33 22	
200			1200	
STREET, ST.			- B - 16	
Contract of the last	- 10° 1.		- 58 (39)	13000
141			- 展 - 93	FEDERAL
Service Same			11	SEED S
property of the second			~# °S	12000

Bid Cost: _		×=	
	Base	Quantity	Total Cost

Repair Category: 14.0 Ceiling

Description

Floor I

Room

Exterior

Ceiling Repair

KITCHEN

Repair ceiling finish. Replace any large areas's of drywall required- match ceiling texture, paint all.

Patch drywall or plaster holes in ceiling greater than one inch. All others use an adhesive mesh and mud over mesh with the appropriate material. Wet sand and smooth.



Bid Cost:	X:		=	
	Base	Quantity	Total Cost	

Repair Category: 16.0 Cabinets, Accessories & Appliances

Description

Floor

Room

Exterior

Cabinets Base

KITCHEN

Replace base cabinets. Cabinets to be constructed of solid maple and plywood. No particle board allowed. See contractor's manual guidelines & specifications for full requirements.

Repair any Upper cabinets which are in need of correction



Bid Cost:		〈 =	
	Base	Quantity	Total Cost

Signature:

Counter Tons Renlace	KITCHEN

Screw to base cabinet a square edged plastic laminate counter top. Provide end-caps and cutout for sink. Caulk counter top to adjoining walls with low VOC caulking to match wall color. Owner's choice of in-stock color and texture. (32.10)

	Bid Cost: _	X Base	= Quantity	Total Cost
Vanity/ Counter Top/ Sink/ Replace Complete			BATHROOM -	MAIN
Install new vanity cabinet complete with counter top of lamina single handled metal faucet with drain and pop-up , P- trap, so				
	Bid Cost:	x	=	
	5.d 000.i	Base	Quantity	Total Cost
Certification			en in America (1994), com en responsa de Propinsion en Legis Andre	
Contractor Name:			Total Cost:	

Date: